

ETHYLENE OXIDE STATEMENT

3808 SODIUM THIOSULPHATE 5-HYDRATE GMP

We hereby confirm that the product referenced above does NOT contain ethylene oxide.

No ethylene oxide, or substances containing ethylene oxide, are intentionally added to the product during the manufacturing process. Furthermore, based on our current knowledge of the raw materials and our processes, no contamination with ethylene oxide is expected.

Esparreguera, July 31st 2024

Laia Galitó
Quality Assurance Technician

