

ETHYLENE OXIDE STATEMENT**1637 RED CONGO SOL. 0,1%**

We hereby confirm that the product referenced above does NOT contain ethylene oxide.

No ethylene oxide, or substances containing ethylene oxide, are intentionally added to the product during the manufacturing process. Furthermore, based on our current knowledge of the raw materials and our processes, no contamination with ethylene oxide is expected.

Esparreguera, July 30th 2024

Laia Galitó
Quality Assurance Technician

